





<p>DATE 11/06/2018 10:13:04 am CUSTOMER Fantech</p>	<p>TYRE TECHNICIAN Jay Porter SITE Brisbane</p>	 <p>FRONT LEFT >2.0 mm FRONT RIGHT >2.0 mm REAR LEFT Under 1.6 mm - Not Roadworthy REAR RIGHT >2.0 mm SPARE TYRE >2.0 mm</p>
<p>REGO 544XIL MAKE/MODEL Kia Sorento ODO. 134,481 km</p>	<p>TYRE TECHNICIAN'S INSPECTION COMMENTS Recommend left rear needs new tyre worn on the inside edge</p>	
<p>TYRE Kumho KL21 SIZE 235/65/17 LOAD RATING 104T</p>	<p>MTS RECOMMENDATIONS Suggest Tyre Replacement with Kumho KL33 (slightly different tread pattern) and Rotate Spare onto vehicle to match \$159. Alternatively, same tyre Kumho KL21 \$259.</p>	

<p>DATE 19/09/201 1:15:04 pm CUSTOMER Vasey RSL Care</p>	<p>TYRE TECHNICIAN Christopher Spicer SITE Ivanhoe</p>	 <p>FRONT LEFT >2.0 mm FRONT RIGHT <2.0 mm REAR LEFT >2.0 mm REAR RIGHT >2.0 mm SPARE TYRE >2.0 mm</p>
<p>REGO WHW759 MAKE/MODEL Toyota Hiace Bus ODO. 20,165 km</p>	<p>TYRE TECHNICIAN'S INSPECTION COMMENTS Wearing more on outer edges. Increased pressure</p>	
<p>TYRE Bridgestone PD-613 Steel SIZE 195/15 LOAD RATING</p>	<p>MTS RECOMMENDATIONS Tyre pressures adjusted onsite. Aranging with contact to rotate the heavily worn tyre into the spare. No Charge.</p>	

<p>DATE 17/04/2019 9:12:05 am CUSTOMER Royal Flying Doctor Service</p>	<p>TYRE TECHNICIAN Lachlan McGillvray SITE Keysborough</p>	 <p>FRONT LEFT Under 1.6 mm - Not Roadworthy FRONT RIGHT Under 1.6 mm - Not Roadworthy REAR LEFT >2.0 mm REAR RIGHT >2.0 mm SPARE TYRE >2.0 mm</p>
<p>REGO ZQN106 MAKE/MODEL Toyota Hiace ODO.</p>	<p>TYRE TECHNICIAN'S INSPECTION COMMENTS Shoulder wear</p>	
<p>TYRE Dunlop SP LT5 SIZE 195r15 LOAD RATING 106/104s</p>	<p>MTS RECOMMENDATIONS Replace 2 tyres and rotate to front. Replacement tyre choices - Budget \$90, Kumho \$130 or Bridgestone \$150 per tyre</p>	

<p>DATE 6/06/2019 10:53:53 am CUSTOMER Achieve Australia</p>	<p>TYRE TECHNICIAN Prav Kumar SITE 16 Collett Parade</p>	 <p>FRONT LEFT >2.0 mm FRONT RIGHT >2.0 mm REAR LEFT Under 1.6 mm - Not Roadworthy REAR RIGHT Under 1.6 mm - Not Roadworthy SPARE TYRE No Access/Not Inspected</p>
<p>REGO SUM17K MAKE/MODEL Toyota Camry ODO.</p>	<p>TYRE TECHNICIAN'S INSPECTION COMMENTS Couldn't take the ODOMETER vehicle was locked no one was on site. Rear tyres shoulder wear</p>	
<p>TYRE Michelin Primacy LC SIZE 215/60/16 LOAD RATING 95V</p>	<p>MTS RECOMMENDATIONS Requires 2 rear tyres: Bridgestone EP300 Authorisation SF864381</p>	